

EAST - [golf cart:2]

FileViewEditToolsWindowHelp

Drafts

IS&R:

BRS:

BRS: bumper with bracket with

BRS:

BRS:

BRS: bipart\$

BRS: l1 and

BRS: l7 and

Pending

Active

L1: (666) (296/204,203.04).CCLS.

L2: (130) l1 and (cut or notch)

L3: (76) l1 and (cut or notch) and (bracket or suspension)

L4: (248) l1 and "280"/\$.ccls.

L5: (61) l4 and side near2 member

L6: (0) suspension near2 mount with side near2 member with

L7: (0) suspension near2 mount with side near2 member with

L8: (0) suspension near2 mount with side near2 member with

L9: (15) suspension near2 mount with side near2 member

Failed

("296/214.ccls.-296/224.ccls.").CCLS.

("296/\$.ccls.").CCLS.

("296/\$.ccls.").CCLS.

"l1" and (stop adj2 block))

M.E.D.

("200/\$.ccls.").CCLS.

("199/\$.ccls.").CCLS.

SearchListBrowseQueueClear

DBsUS-PGPUB:Plurals

Default operator:ORHighlight all hit terms initially

suspension near2 mount with side near2 member

Custom formBRS formIS&R formHits

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (7)

UDC

Queue

Trash

	U	1	Document ID	Issue Dat	Page	Title	Current C
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6648401 B2	20031118	10	Motor vehicle body with wheelhouse/underbody re.	296/198
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6434907 B1	20020820	15	Closed channel structural member havin	52/731.6
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6270152 B1	20010807	12	Vehicle body structure	296/203.0
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5567005 A	19961022	13	Car body work sub-frame mounting structure	296/204
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5549350 A	19960827	21	Rear underbody structure	296/204
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5468018 A	19951121	7	Torque box assembly for a vehicle	280/788
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4708391 A	19871124	6	Rear body structure for motor vehicle	296/204

HitsDetailsHTML

NUM

ST AVAILABLE COPY

EAST - [golf cart:2]

FileViewEditToolsWindowHelp

Drafts

IS&R:

BRS:

BRS: bumper with bracket with

BRS:

BRS:

BRS: bipart\$

BRS: l1 and

BRS: l7 and

Pending

Active

L1: (666) (296/204,203.04).CCLS.

L2: (130) l1 and (cut or notch)

L3: (76) l1 and (cut or notch) and (bracket or suspension)

L4: (248) l1 and "280"/\$.ccls.

L5: (61) l4 and side near2 member

L6: (0) suspension near2 mount with side near2 member with

L7: (0) suspension near2 mount with side near2 member with

L8: (0) suspension near2 mount with side near2 member with

L9: (15) suspension near2 mount with side near2 member

Failed

("296/214.ccls.-296/224.ccls.").CCLS.

("296/\$.ccls.").CCLS.

("296/\$.ccls.").CCLS.

"l1" and (stop adj2 block))

M.E.D.

("200/\$.ccls.").CCLS.

("199/\$.ccls.").CCLS.

SearchListBrowseQueueClear

DBsUS-PGPUBPlurals

Default operator: ORHighlight all hit terms initially

suspension near2 mount with side near2 member

Custom formBRS formIS&R formHits

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (7)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error I
1	IS&R	L1	666	(296/204,203.04).CCLS	US-P GPUB	2005/01/1 1 08:47		
2	BRS	L2	130	l1.and (cut or notch)	US-P GPUB	2005/01/1 1 08:47		
3	BRS	L3	76	l1 and (cut or notch) and (bracket or suspe	US-P GPUB	2005/01/1 1 08:49		
4	BRS	L4	248	l1 and "280"/\$.ccls.	US-P GPUB	2005/01/1 1 08:50		
5	BRS	L5	61	l4 and side near2 member	US-P GPUB	2005/01/1 1 08:52		
6	BRS	L6	0	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		
7	BRS	L7	0	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		
8	BRS	L8	0	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		
9	BRS	L9	15	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		

Hits

Details

HTML

Ready

NUM

T AVAILABLE COPY